

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




FIGURE 1

200




FIG. 2




FIG. 3A




Fig. 3B





Fig 4



500

Fig 5





Fig. 6

704  
703



702

Fig. 7






Fig - 8

802




Fig 9

900





Fig. 10



} 1102

Fig. 11




Fig. 12






Fig. 13

## Cup and Liner Selection

40	42	44	46	48	50	52	54
56	58	60	62	64	66	68	70


MH Rad 3-Hole	Univ MultiHole	Other
------------------	-------------------	-------

MaxROM	10°	+5mm
--------	-----	------

close

1480

Fig. 1014



L1500

Fig. 15







Fig. 16



L1700

Fig. 17